


Passed fibers – Tray1




All fibers – Tray1




Passed fibers – Tray2




All fibers – Tray2

Summary of Pigtail Quality Control




Passed fibers – Tray3




All fibers – Tray3




Passed fibers – Tray4




All fibers – Tray4




Passed fibers – Tray5




All fibers – Tray5

Summary of Pigtail Quality Control




Passed fibers – Tray6




All fibers – Tray6




Passed fibers − Tray1−3




All fibers − Tray1−3

Summary of Pigtail Quality Control




Passed fibers − Tray4−6




All fibers − Tray4−6




Passed fibers – All trays




All fibers – All trays

Summary of Pigtail Quality Control




Failed fibers – Tray1




Failed fibers – Tray2




Failed fibers – Tray3




Failed fibers – Tray4

Summary of Pigtail Quality Control




Failed fibers – Tray5




Failed fibers – Tray6




Failed fibers – Tray1–3




Failed fibers – Tray4–6


Summary of Pigtail Quality Control
ID 910
Entries 310
Mean 1.004
RMS 0.2210
30
25
20
15
10
5
0
0.5
0.75
1
1.25
1.5
Failed fibers – All trays