Summary of Pigtail Quality Control for R1L1



Passed fibers – Tray1



All fibers – Tray1



Passed fibers – Tray2



All fibers – Tray2



Passed fibers – Tray3



All fibers – Tray3

Summary of Pigtail Quality Control for R1L1



Passed fibers – Tray4



All fibers – Tray4

Summary of Pigtail Quality Control for R1L1



Passed fibers – Tray5



All fibers – Tray5

Summary of Pigtail Quality Control for R1L1



Passed fibers – Tray6



All fibers – Tray6



Passed fibers – Tray1–3



All fibers – Tray1–3



Passed fibers − Tray4−6



All fibers − Tray4−6

Summary of Pigtail Quality Control for R1L1



Passed fibers – All trays



All fibers – All trays

Summary of Pigtail Quality Control for R1L1



Failed fibers – Tray1



Failed fibers – Tray2



Failed fibers – Tray3



Failed fibers – Tray4

Summary of Pigtail Quality Control for R1L1



Failed fibers – Tray5



Failed fibers – Tray6



Failed fibers – Tray1–3



Failed fibers – Tray4–6


Summary of Pigtail Quality Control for R1L1
ID 910
Entries 67
Mean 0.9690
RMS 0.2109
0
1
2
3
4
5
6
0.5
0.75
1
1.25
1.5
Failed fibers – All trays